Service & Repair History

Check Records

Accident & Title History

Check Records

Market Value Fair Price

Check Records

Odometer Records Check

Check Records

VIN: 1GBLP37J9W3311057

Year: 1998 Make: Chevrolet Model: P30

Details info. on VIN: 1GBLP37J9W3311057

Year: 1998

Make: Chevrolet

Model: P30

Vehicle_type: Van

Drive_type: RWD

Doors: 0

Msrp: $16,554

Transmission_style: Manual

Power_steering: Standard

Engine_description: V-8 7.4L

Engine_capacity: 7.4 L

Fuel_type: Gasoline

Manufacturer: General Motors Corporation

Country: United States

Vin: 1GBLP37J9W3311057

Engine_size: 7.4

Engine_number_of_cylinders: 8

Displacement_(ci): 454

Source: USDecode

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

View our Sample Window Sticker

Get your Windows Sticker



SERVICE MAINTENANCE RECORDS

For your Vehicle **1998 CHEVROLET P30**

At the Mileage of **55000 mi**

Against the **VIN 1GBLP37J9W3311057**

A QUICK SUMMARY OF YOUR VEHICLE

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

SAFETY RECALLS 2 items

Your vehicle has 2 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

→ View your recall notices here.

WARRANTY STATUS

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

- ✕ Basic new car warranty 3 years
- ✕ Powertrain warranty 3 years
- ✕ Federal emissions warranty 8 years

- If the vehicle is covered.
- If the vehicle is not completely covered.
- If the vehicle is not covered.

UPCOMING ISSUES 2 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

36%	27%
Likelihood of	Likelihood of
Replace Mass Air Flow (MAF) Sensor	Replace Oxygen Sensor(s) (O2S)
$443	$223
Cost of repair	Cost of repair
$341 in parts	$121 in parts
$102 in labor	$102 in labor
Repair difficulty	Repair difficulty





This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

This Premium VIN Report is based only on information acquirable by Premium VIN as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Premium VIN. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2026 Premium VIN. All Rights Reserved.