Service & Repair History

Check Records

Accident & Title History

Check Records

Market Value Fair Price

Check Records

Odometer Records Check

Check Records

VIN: 1XPXD49X9BD129116

Year: 2011 **Make:** Peterbilt **Model:** 389

Details info. on VIN: 1XPXD49X9BD129116

Year: 2011

Make: Peterbilt

Body_type: Truck-Tractor

Model: 389

Vehicle_type: Air-Braked Vehicle

Drive_type: Tractor 6x4

Doors: 2

Engine_description: ISX15

Engine_capacity: ISX15 L

Fuel_type: Diesel

Manufacturer: Paccar

Country: Manufactured In The United States

Vin: 1XPXD49X9BD129116

Engine_number_of_cylinders: 6

Engine_manufacturer: Cummins

Displacement_(cc): 15000

Displacement_(ci): 915.3561614209

Displacement_(l): 15

Engine_model: ISX

Engine_configuration: In-Line

Region: Denton, Tx

Note: Gvwr (lbs): 47,001-57,000

Gvwr: Class 8: 47,001-57,000lbs

Source: USDecode

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

View our Sample Window Sticker

Get your Windows Sticker



SERVICE MAINTENANCE RECORDS

For your Vehicle **2011 PETERBILT 389**

At the Mileage of **45000 mi**

Against the **VIN 1XPXD49X9BD129116**

A QUICK SUMMARY OF YOUR VEHICLE

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

SAFETY RECALLS 9 items

Your vehicle has 9 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

→ View your recall notices here.

This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

This Premium VIN Report is based only on information acquirable by Premium VIN as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Premium VIN. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2026 Premium VIN. All Rights Reserved.