



Vehicle History Report

Report Generated: 04-18-2021

[Copy Link](#) | [Download](#)



2003 YAMAHA YZF-R1/YZF-R1C/YZF-R1

VIN: JYARN10Y73A001659
Year: 2003
Make: YAMAHA
Model: YZF-R1/YZF-R1C/YZF-R1

Vehicle Age
18 Years

Exterior
Blue

SNAPSHOT OF YOUR VEHICLE



Accident Check
Accident Reported



Loan/Lien Check
No Record Found



Title Check
Salvage



Usage
Personal Use



Damage
Damage Record Found



Color
Blue

AUCTION RECORDS



Title & Condition

Title Type	Salvage
Title Description	CA - Salvage Certificate
Primary Damage	All Over
VIN	JYARN10Y73A001659

[Runs-&Drives](#) | [Engine-Starts](#) | [Has-Keys](#)

Sale Status
\$400 Sold

SOLD

Technical Specs

Avg. Estimated Retail Value :	\$4,279
Body Style :	Motorcycle
Color :	Blue
Cylinders :	4
Damage Ratio :	163%
Engine Type :	4
Estimated Repair Cost :	\$9,288
Estimated Winning Bid :	\$1,022 - \$1,248
Fuel Type :	Gas
Transmission :	Manual

Auction Info

Auction Type	Pure Sale
Seller Type	Insurance Companyhelp_outline
Auction Date	November 27, 2020 3:48 PM CST
Location	Wilmington, California
Buyer Country	United States

Vehicles Sales History

No previous auction found!

VEHICLE SPECIFICATIONS

Destination market: California	Make: YAMAHA
Manufacturer name: YAMAHA MOTOR CORPORATION	Model: YZF-R1/YZF-R1C/YZF-R1
Model year: 2003	Plant city: HAMAMATSU

Model year: 2005	Plant city: HAMAMATSU
Vehicle type: MOTORCYCLE	Plant country: JAPAN
Body class: Motorcycle - Sport	Gross vehicle weight rating from: Class 1A: 3,000 lb or less (1,360 kg or less)
Displacement (cc): 1000	Displacement (ci): 61.023744094
Displacement (l): 1.000000	Ncsa body type: Two Wheel Motorcycle (excluding motor scooters)
Ncsa make: Yamaha	Ncsa model: 750cc or greater
Engine name: 4	Transmission: MANUAL
Exterior color: Blue	

DETAILED HISTORY VERIFICATION

Event Date	Location	Odometer Reading	Data Source	Details
08/31/2021			TBD	Oil Change
11/18/2020			Incident Record	All Over

Window Sticker

Learn more with a Window Sticker

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.

[Sample Window Sticker](#)

[Order Window Sticker](#)



SERVICE MAINTENANCE RECORDS

At the Mileage of 50000 miles

Against the VIN JYARN10Y73A001659



A QUICK SUMMARY OF YOUR VEHICLE

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

This service is due at 50000 mi

RECALLS & COMPLAINTS

No Recalls & Complaints Found.