



Vehicle History Report

Report Generated: 01-15-2021

[Copy Link](#) | [Download](#)

VIN: **WMWLN9C52H2E49013**

DETAILED HISTORY VERIFICATION

Event Date	Location	Odometer Reading	Data Source	Details
09/21/2021	N/A	42,500 mi	Motor Vehicle Dept.	Current estimated mileage
07/31/2021	KY		Motor Vehicle Dept.	Upcoming Registration Date
07/31/2020	KY	44,274 mi	Kentucky Motor Vehicle Dept. Louisville, KY	SALVAGE TITLE/CERTIFICATE ISSUED
04/03/2019	KY		Tire Discounters Louisville, KY 502-814-6142	Vehicle serviced Tire repaired Tire(s) replaced Tire condition and pressure checked Tire(s) replaced
09/08/2018	KY	16,979 mi	Valvoline Instant Oil Change Louisville, KY 502-361-2583	Vehicle serviced Fluids checked
04/23/2018	KY	11,843 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced Maintenance inspection completed
12/14/2017	KY		MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced Pre-delivery inspection completed Maintenance inspection completed Vehicle washed/detailed
10/11/2017	KY	9,803 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced Maintenance inspection completed Windshield replaced
09/15/2017	KY	9,345 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced Maintenance inspection completed Oil and filter changed Vehicle washed/detailed
06/26/2017	KY	6,020 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced One tire mounted One tire balanced
04/28/2017	KY	4,307 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced
08/22/2016	KY	6 mi	MINI of Louisville Louisville, KY 502-893-7770	Vehicle serviced Floor mats installed



Sale Status

\$7,600 Sold

SOLD

Auction Info

Auction Type	On Approval
Seller Type	Insurance Companyhelp_outline
Auction Date	August 20, 2020 9:00 AM CDT
Location	Louisville, Kentucky

Vehicles Sales History

No previous auction found!

Title & Condition

Title Type	Salvage
Title Description	KY - Cert Of Title-Salvage
Primary Damage	Front End
Secondary Damage	Minor Dent/scratches

VIN

WMWLN9C52H2E49013

Technical Specs

Body Style :	Wagon
Color :	Black
Cylinders :	4
Damage Ratio :	66%
Drive :	Front-Wheel Drive
Engine Type :	2.0L 4
Estimated Repair Cost :	\$12,611
Estimated Winning Bid :	\$6,787 - \$8,295
Fuel Type :	Gas
Odometer :	44,274 miles, Actual
Transmission :	Automatic

SELLING VEHICLE